Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 8/5/2014	Man Days: 1
Inspection Unit: Springfield	·
Location of Audit:	
Exit Meeting Contact:	
Inspection Type: Standard Inspection - Record Audit	
Pipeline Safety Representative(s): Kevin Hecker	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Robert Roth	Senior Quality Assurance Consultant	

Gas System Operations	Status
Gas Transporter	Ameren Illinois
Annual Report (Form 7100.1-1) reviewed for the year:	Not Checked
General Comment:	
Staff reviewed Ameren's annual report (covering all legacy companies and operating centers) during the Annual Report audit conducted at Springfield, IL. No issues were identified during that audit.	the ICC office in
Unaccounted for Gas	.53%
Number of Services	825576
Miles of Main	16888
Is the operator maintaining documentation verifying their Maximum Allowable Operating Pressure(s)? (MAOP)	Not Checked
General Comment:	

MAOP records are housed at Decatur Plaza and were reviewed	d during a previous audit.	
Operating Pressure (Feeder)		varies by area
Operating Pressure (Town)		varies by area
Operating Pressure (Other)		Not Applicable
General Comment:		
Ameren identifies their pipeline as transmission or distribution.		
MAOP (Feeder)		varies by area
MAOP (Town)		varies by area
MAOP (Other)		Not Applicable
General Comment:		
Ameren identifies their pipeline as transmission or distribution.		
Does the operator have any transmission pipelines	5?	Yes
Regulatory	Reporting Records	Status
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Not Applicable
General Comment:		
There were no reportable incidents within the Springfield Opera	ating Center's territory in 2012 or 2013.	
[191.9(a)]	Was a DOT Incident Report Form F7100.1 submitted within 30 days after detection of an incident?	Not Applicable
General Comment:		
There were no reportable incidents within the Springfield Opera	ating Center's territory in 2012 or 2013.	
[191.9(b)]	Were any supplemental incident reports submitted when deemed necessary?	Not Applicable
General Comment:		
There were no reportable incidents within the Springfield Opera	ating Center's territory in 2012 or 2013, therefore no supplemental reports w	ere required.
Did the operator have any plastic pipe failures in the	ne past calendar year?	No
General Comment:		
Ameren's Springfield Operating Center experienced no plastic	oipe failures in 2012 or 2013.	
Did the operator take action to mitigate safety concomponents?	cerns relating to the failure of the PE or pipeline	No
General Comment:		
Ameren's Springfield Operating Center experienced no plastic	pipe failures in 2012 or 2013.	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[191.23(a)]	Did the operator report Safety Related Conditions?	Not Applicable
General Comment:	<u> </u>	
Ameren's Springfield Operating Center experienced no	o safety related conditions in 2012-2013.	
[191.25]	Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than 10 working days after discovery?	Not Applicable
General Comment:	<u> </u>	•
Ameren's Springfield Operating Center experienced no	o safety related conditions in 2012-2013.	
[192.16(c)]	Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location?	Satisfactory
General Comment:	•	
Ameren Illinois sends all new customers notification of distributed as part of Ameren's Public Awareness Plan	responsibility at the time the customer signs up for service. This notification is in add	dition to any brochures
	DRUG TESTING	Status
Category Comment:		
A review of Ameren's drug and alcohol plan was comp	leted in 2011 and not part of this audit.	
Refer to Drug and Alcohol Inspection Forms	s and Protocols	Not Checked
TE	ST REQUIREMENTS	Status
[192.517(a)][192.505,192.507,192.511(c)]	Are pressure test records being maintained for piping operating above 100 psig?	Not Checked
General Comment:		•
High pressure distribution and transmission records ar	e housed at Decatur Plaza and were reviewed during a previous audit.	
[192.517(b)][192.511,192.509,192.513]	Are pressure test records being maintained for at least 5 years on piping operating below 100 psig?	Satisfactory
General Comment:	•	
Staff requested several randomly chosen service cards being maintained.	s. The service cards reviewed demonstrated that proper testing was conducted and	testing records are
[192.603(b)][192.725]	Were service lines temporarily disconnected from the main properly tested prior to reconnection?	Satisfactory
	UPRATING	Status
Category Comment:	UPRATING	Status
Category Comment: No uprating was performed within the Ameren Springfi		Status

AMEREN ILLINOIS COMPANY/8-6-2014

Page 3 of 15

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	activities when uprating a pipe to a pressure that will	
	produce a hoop stress of 30% or more SMYS?	
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Not Applicable
	OPERATIONS	Status
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Not Checked
General Comment:		
The operator was able to provide records from to during a previous audit at the Pawnee Operating	he Subject Matter Reference Meetings that were conducted throughout 2013. These record g Center in February 2014.	ds were reviewed
Has the operator conducted a review c	of the Operator Qualification Plan once per yr/15 months?	Not Checked
General Comment:		
The operator was able to show that the OQ plan Pawnee Operating Center in February 2014.	review is part of the Subject Matter Reference Meetings. These records were reviewed du	ıring an audit at the
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Satisfactory
General Comment:		
The laptops in each truck contain the records an operating history information at the Operating Co	nd maps of the gas system, as well as some of the operating history. Supervisors have accounter if necessary.	ess to additional
[192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to determine the effectiveness of normal O&M procedures when deficiencies are found?	Not Checked
General Comment:	<u> </u>	
This is done by Quality Assurance Personnel an Operating Center audit conducted in February 2	d supervisors during company field audits. Staff reviewed 2013 Quality Assurance Results 014.	during the Pawnee
CONTIN	IUING SURVEILLANCE RECORDS	Status
[192.603(b)][192.613(a)]	Has the operator reviewed continuing surveillance records for class location changes, failures, leak history, corrosion, changes in cathodic protection, and other unusual operating and maintenance conditions?	Not Checked
General Comment:	<u> </u>	•
This information is housed and currently being re	eviewed at the Decatur Plaza operating center.	
[192.491][192.489]	Does the operator have records verifying if exposed cast iron was examined for evidence of graphitization and if necessary what appropriate action was taken concerning graphitization?	Not Applicable
General Comment: There is no cast iron pining within Ameren Sprin	graphitization?	
<u>mment:</u> east iron piping within Ameren Sprin	gfield's operating territory.	

AMEREN ILLINOIS COMPANY/8-6-2014

Page 4 of 15

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.603(b)][192.755]		
	Does the operator have surveillance records of cast iron pipelines, including appropriate action resulting from tracking circumferential cracking failures, study of leak history, or any other unusual operating and maintenance conditions?	Not Applicable
General Comment:	<u> </u>	
There is no cast iron piping within Ameren Spr	ingfield's operating territory.	
[192.603(b)][192.753(a)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of more than 25 (psig.) sealed as required?	Not Applicable
General Comment:	•	
There is no cast iron piping within Ameren Spr	ingfield's operating territory.	
[192.603(b)][192.753(b)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of 25 (psig.) or less and is exposed for any reason sealed as required?	Not Applicable
General Comment:	<u> </u>	•
There is no cast iron piping within Ameren Spr	ingfield's operating territory.	
OHALIE	ICATION OF PIPELINE PERSONNEL	Status
QUALII		
Category Comment:	IOATION OF THE PENCE TENCOMINEE	
·		
Category Comment:	I records was not part of this audit.	Not Checked
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspec	I records was not part of this audit.	Not Checked Status
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspec	I records was not part of this audit. tion Forms and Protocols	
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspector DAI Category Comment:	I records was not part of this audit. tion Forms and Protocols	
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspector DAI Category Comment: These records were reviewed during a record of the comment:	tion Forms and Protocols MAGE PREVENTION RECORDS	
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspector DAI Category Comment:	tion Forms and Protocols MAGE PREVENTION RECORDS audit at the Pawnee Operating Center in February 2014. Did the operator track the number of damages per 1000 locate requests for the previous years?	Status
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspector DAI Category Comment: These records were reviewed during a record of [192.603(b)][191.11(a)] Has the number of damages increase	tion Forms and Protocols MAGE PREVENTION RECORDS audit at the Pawnee Operating Center in February 2014. Did the operator track the number of damages per 1000 locate requests for the previous years?	Status Not Checked
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspector DAI Category Comment: These records were reviewed during a record of [192.603(b)][191.11(a)]	tion Forms and Protocols MAGE PREVENTION RECORDS audit at the Pawnee Operating Center in February 2014. Did the operator track the number of damages per 1000 locate requests for the previous years? Ed or decreased from prior year? Does the operator track records of accidents due to excavation damage to ensure causes of failures are	Not Checked Not Checked
Category Comment: A review of the Operator Qualification plan and Refer to operator Qualification Inspector DAI Category Comment: These records were reviewed during a record of [192.603(b)][191.11(a)] Has the number of damages increase [192.603(b)][192.617] [192.603(b)][192.614(c)(3)]	A records was not part of this audit. Ition Forms and Protocols MAGE PREVENTION RECORDS Audit at the Pawnee Operating Center in February 2014. Did the operator track the number of damages per 1000 locate requests for the previous years? End or decreased from prior year? Does the operator track records of accidents due to excavation damage to ensure causes of failures are addressed to minimize the recurrence? Does the operator provide documentation pertaining to notification of excavation, marking, positive response, and	Not Checked Not Checked Not Checked

AMEREN ILLINOIS COMPANY/8-6-2014

Page 5 of 15

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Not Checked
Has the Operator adopted applicable sect	ons of the Common Ground Alliance Best Practices?	Not Checked
If no, were Common Ground Alliance Best	If no, were Common Ground Alliance Best Practices discussed with Operator?	
	EMERGENCY PLANS	Status
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Satisfactory
General Comment:		
The Emergency Plan is reviewed January of each ye	ear by all company employees. All employees have access to the emergency plan at all	ll times.
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	Satisfactory
General Comment:	•	
Ameren documents training, including emergency tra	aining, with an electronic online system.	
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Satisfactory
General Comment:		
Reviews are conducted and documented by supervissituations in 2012-2013.	sors as well as QA personnel after an emergency. Ameren Springfield did not experien	ce any emergency
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Satisfactory
General Comment:		
This documentation was reviewed during a previous	audit at the Pawnee Operating Center in February 2014.	
[192.603(b)][192.615(a)(3)]	Did the review of emergency response time intervals regarding odor/leak complaint documentation indicate adequate emergency response intervals were achieved?	Satisfactory
General Comment:		
Staff reviewed emergency response intervals during	a previous audit at Ameren's Pawnee operating center.	
PUBLIC AWA	ARENESS PROGRAM - RECORDS	Status
Category Comment: A review of Ameren Illinois' Public Awareness Progra	am was conducted at the Pawnee operating center in February 2014.	

AMEREN ILLINOIS COMPANY/8-6-2014

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Refer to Public Awareness Program Ins	spection Forms and Protocols	Not Checked
	ODORIZATION OF GAS	Status
[192.603(b)][192.625(f)]	Has the operator maintained documentation of odorant concentration level testing using an instrument?	Satisfactory
General Comment:		
The operator was able to provide documentation	indicating that odorant concentration level testing was conducted utilizing Heath Odorators	S
[192.603(b)][192.625(e)]	Has the operator maintained documentation of odorizer tank levels?	Satisfactory
General Comment:	<u> </u>	
Staff reviewed documentation of odorant tank lev	vels for 2012-2013. No deficiencies were discovered.	
[192.603(b)][192.625(f)(1)]	Are master meter operators receiving written verification of odorant concentration levels from their gas supplier?	Not Applicable
General Comment:		
Ameren Springfield is not a master meter operate	or.	
[192.603(b)][192.625(f)(2)]	Has the master meter operator maintained documentation of sniff tests performed as required by this section?	Not Applicable
General Comment:	<u> </u>	
Ameren Springfield is not a master meter operate	or.	
PATR	ROLLING & LEAKAGE SURVEY	Status
[192.603(b)][192.721(b)(1)]	Is the operator patrolling business districts at a minimum of 4 per year/4 1/2 months?	Not Applicable
General Comment:		
Ameren Springfield has determined that busines	s district surveys are only required once annually.	
[192.603(b)][192.721(b)(2)]	Is the operator patrolling outside business districts at a minimum of 2 per year/7 1/2 months?	Not Applicable
General Comment:	•	
There are no pipelines within Ameren Springfield	d's operating territory that apply to this code part.	
[192.603(b)][192.723(b)(1)]	Is the operator performing leakage surveys in business districts at a minimum of 1 per year/ 15 months? If the operator has inside meter sets that meet this criterion then were those surveyed?	Satisfactory
General Comment:		
Staff reviewed Leakage Survey records for 2012	- 2013. In order to determine if inside meter sets were included in the survey, addresses of y records. No deficiencies were found. There are 70 inside meter sets within the Ameren S	
	y records. No denoterates were round. There are 70 inside meter sets within the Ameren C	spinighera operating

AMEREN ILLINOIS COMPANY/8-6-2014

Page 7 of 15

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment: There are 70 inside meter sets and they are surveyed on a 3	business district at a minimum of every 5 years/63 months? Is the operator performing leakage surveys on cathodically unprotected pipelines at a minimum of every 3 years/39 months? If the operator has inside meter sets that meet this criterion then were those surveyed? If the operator has yard lines then are those being surveyed? year cycle. Yard lines are surveyed up to the structure wall.	
YARD LIN	IES - RESIDENTIAL	Status
[220 ILCS 2.2.03]	Has the operator designated and documented the location of all services where the meter is located more than 3 feet away from the wall of a residence?	Satisfactory
[192.463,220 ILCS 2.2.03][220 ILCS 2.2.03]	Has the operator determined if cathodic protection is required on these services?	Satisfactory
[192.723(b)(1),192.723(b)(2)][220 ILCS 2.2.03]	After the determination of the cathodic protection requirements, has the operator surveyed each line within the required leakage survey intervals?	Satisfactory
ABANDONMENT or DEACTI	VATION of FACILITIES PROCEDURES	Status
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected from all sources and supplies of gas, and purged of gas?	Satisfactory
General Comment:		
No pipeline was abandoned in 2012-2013.		
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and supplies of gas; purged of gas?	Satisfactory
General Comment:		
Separate documentation for purging is done only on high presis not done for distribution.	ssure distribution and transmission lines. Engineering typically writes up a "pui	ge plan", however this
[192.603(b)][192.727(d)]	Did the operator maintain documentation demonstrating that whenever service to a customer was discontinued access to gas was either; locked, prevented by a mechanical fitting, or disconnected from the gas supply and open pipe ends sealed?	Satisfactory
General Comment:		
Ameren uses a computerized service order system to record	services that are locked off and the method used. (typically services are pin-lo	cked)
[192.603(b)][192.727(e)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging?	Satisfactory

AMEREN ILLINOIS COMPANY/8-6-2014

Page 8 of 15

General Comment:		
Separate documentation for purging is done only on high pre is not done for distribution.	ssure distribution and transmission lines. Engineering typically writes up a "pui	rge plan", however this
[192.727(g)][192.727(g)]	Did the operator maintain documentation for each abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable
General Comment:		
There are no commercially navigable waterways within the A	meren Springfield operating territory.	
PRESSURE LIN	IITING AND REGULATION	Status
[192.603(b)][192.739(a)]	Is the operator inspecting and testing the pressure limiting and regulating stations at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff reviewed regulator inspections for 2012-2013.		
[192.603(b)][192.743(a)]	Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff was able to confirm regulators are checked annual for o	capacity. These inspections are listed as "engineering evaluations" in Ameren's	GCS system.
[192.603(b)][192.743(b)]	If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months?	Satisfactory
General Comment:	-	
Staff was able to confirm regulators are checked annual for o	capacity. These inspections are listed as "engineering evaluations" in Ameren's	GCS system.
[192.603(b)][192.741(a),192.741(b)]	Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating station, equipped with telemetering or recording pressure gauges to indicate the gas pressure in the district?	Satisfactory
General Comment:		
Staff reviewed telemetering records for 2012-2013.		
[192.603(b)][192.741(c)]	If there were indications of abnormally high- or low- pressure, were actions taken to correct any unsatisfactory operating conditions?	Not Checked
General Comment:		
These records are housed at Decatur Gas Control. A review	of these records will be conducted at a later date.	
[192.603(b)][192.743(a),192.743(b),192.195(b)(2	ls overpressure protection provided by the supplier pipeline downstream of the take point?	Yes

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
Each take point within the Ameren Springfield's operat	ting territory is protected by an over pressure relief valve.	
[192.603(b)][192.743(a)]	If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Satisfactory
General Comment:		
Staff was able to confirm relief valves are checked ann	nually for capacity. These inspections are listed as "engineering evaluations" in Amer	en's GCS system.
VA	ALVE MAINTENANCE	Status
[192.603(b)][192.747(a),192.747(b)]	Did the operator inspect and maintain distribution valves necessary for the safe operation of the system at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff reviewed valve inspections from 2012-2013 with	no issues identified.	
[192.603(b)][192.749(a)]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Not Applicable
General Comment:		
There are no vaults larger than 200 cubic feet within A	meren Springfield's operating territory.	
Inv	estigation Of Failures	Status
[192.603(b)][192.617]	Did the operator experience accidents or failures requiring analysis?	Not Applicable
General Comment:	-	
Ameren Springfield did not experience any accidents o	or failures requiring analysis.	
WEI	LDING OF STEEL PIPE	Status
[192.603(b)][192.225(b)]	Does the operator have documentation for their qualified welding procedure?	Satisfactory
General Comment:		
The operator's welding procedures are included in the	O&M in the section titled, WELD - Welding.	
[192.603(b)][192.227,192.229]	Does the operator have documentation of welder qualification as required?	Not Checked
General Comment:		
Staff reviewed documentation of welder qualification/re	e-qualification during a record audit at the Pawnee Operating Center in February 201	4.
[192.709][192.243(b)(2)]	Does the operator have documentation of NDT personnel qualification as required?	Not Checked
General Comment:		
The NDT records were reviewed at a previous audit at	t Decatur Plaza.	

AMEREN ILLINOIS COMPANY/8-6-2014

Page 10 of 15

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.709][192.243(f)]	Does the operator have documentation of NDT testing performed?	Not Checked
General Comment:		
The NDT records were reviewed at a previous aud	lit at Decatur Plaza.	
JOINING OF MATERIAL OTHER THAN WELDING		Status
[192.603(b)][192.285]	Are persons making joints with plastic pipe qualified?	Satisfactory
General Comment:	·	
The operator was able to provide documentation of Operating Center in February 2014.	of qualification for persons inspecting plastic joints. These records were reviewed during a	n audit at the Pawnee
[192.603(b)][192.287]	Are persons inspecting plastic pipe joints qualified?	Satisfactory
General Comment:		
The operator was able to provide documentation of Operating Center in February 2014.	f qualification for persons inspecting plastic joints. These records were reviewed during a	n audit at the Pawnee
[192.603(b)][192.283]	Are qualified joining procedures for plastic pipe in place?	Satisfactory
General Comment:	·	
The joining procedures are located in section "POL	LY - Polyethylene Pipe" of the operator's O&M	
CORROSION CONTROL RECORDS		Status
[192.491(a)][192.491(a)]	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system?	Satisfactory
General Comment:		
Staff reviewed GCS maps for the Springfield area,	as well as records identifying bonds, adjacent metallic structures, etc. No deficiencies we	ere identified.
[192.491][192.459]	Has the operator maintained documentation of an examination when buried pipe was exposed?	Satisfactory
General Comment:		
Staff reviewed several buried pipe examination for	ms with no deficiencies identified.	
[192.491][192.465(a)]	Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100 feet at a minimum of 10% annually?	Satisfactory
General Comment:		
Staff was able to review Ameren's CTS Corrosion	tracking system and spot checked several rectifier inspections. No deficiencies were four	nd.
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Satisfactory

AMEREN ILLINOIS COMPANY/8-6-2014

Page 11 of 15

General Comment:		
Staff was able to review Ameren's CTS Corrosion tracking	system and spot checked several rectifier inspections. No deficiencies were four	nd.
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff was able to review Ameren's CTS Corrosion tracking	system and spot checked documentation pertaining to interference bonds. No de	eficiencies were found
[192.491][192.465(d)]	Has the operator taken prompt remedial actions to correct any deficiencies indicated by the monitoring?	Not Applicable
General Comment:		
No deficiencies were discovered during this record audit.		
[192.491][192.465(e)]	Has the operator maintained documentation of unprotected pipeline surveys, inspections, or tests at a minimum of 3 years/39 months?	Satisfactory
General Comment:		
There is no unprotected pipeline within Ameren Springfield	's territory.	
[192.491][192.467(a),192.467(c),192.467(d)]	Has the operator maintained documentation of inspections or tests for electrical isolation at casings?	Satisfactory
General Comment:		
Staff reviewed the corrosion records for casings. All records	s that were reviewed indicated that isolation and CP readings are taken annually	at casings.
[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic protection?	Satisfactory
[192.491][192.471]	Has the operator maintained documentation of corrective actions taken when a test lead is no longer electrically conductive?	Satisfactory
General Comment:		
There were no instances of test leads becoming electrically	unconductive in 2012-2013.	
[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not affecting adjacent underground metallic structures?	Satisfactory
General Comment:		
Ameren identifies these as "adjacent foreign crossings", an	d check them annually.	
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion	Not Checked

	due to transportation of corrosive gas?	
General Comment:		
Corrosion records including coupons are housed at Decatur	Plaza. These records were reviewed during a previous audit.	
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Not Checked
General Comment:	<u> </u>	
Corrosion records including coupons are housed at Decatur	Plaza. These records were reviewed during a previous audit.	
[192.491][192.477]	Has the operator maintained documentation of internal corrosion coupon monitoring at a minimum of 2 per year/ 7 1/2 months?	Not Checked
General Comment:		
Corrosion records including coupons are housed at Decatur	Plaza. These records were reviewed during a previous audit.	
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/ 39 months?	Satisfactory
General Comment:	<u> </u>	
The operator completes atmospheric corrosion surveys as p disbonded coating, need for paint, condition/position of riser	part of leak surveys. The documentation from the leak survey "daily sheets" incl ;, etc.	ude details such as
[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory
General Comment:	<u> </u>	
Staff reviewed documentation of atmospheric corrosion issu number associated with the issue to verify work was comple	es identified during a previous leak survey, then used the GCS system to track eted.	the work order
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation demonstrating that pipe removed due to external corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	Not Applicable
General Comment:	<u> </u>	
No pipe in the Ameren Springfield operating territory was real. The O&M stipulates that cathodic protection is applied to the	moved due to external corrosion, however, all steel repair pipe used in Ameren e repaired pipeline within 1 year.	's system is coated.
TRAINING - 83 IL ADM. CODE 520		Status
[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Satisfactory
General Comment:	·	
Ameren Illinois utilizes an electronic records system of traini next training session is due.	ing completed. This shows all company training, date of completion and include	es reminders for when
[520.10(a) (2)]	Do training records include verbal instruction and/or on the job training for each job classification?	Satisfactory

General Comment:		
These training records were reviewed in P	awnee Operating Center during a previous audit in February 2014.	
[520.10(b)]	Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Applicable
General Comment:		
Ameren Springfield is not a municipal ope	rator.	
[520.10(a)(5)]	Are procedures periodically updated to include new materials, new methods of operation and installation, and changes in general procedures?	Satisfactory
General Comment:	<u>.</u>	•
Updates to procedures are released bi-and	nually. These updates include new materials, new methods of operation and installation, and ger	neral procedures.

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

AMEREN ILLINOIS COMPANY/8-6-2014 Page 15 of 15